



- Suppression Repair Points**
- Point Type, Repair Status
 - Ridge, Repair Needed
 - Chipping Blows, Repair Needed
 - Covert Damage, Completed - Approved
 - Covert Damage, Repair Needed
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Drop Pile, Repair Needed
 - Drop Pile, Completed - Approved
 - Equipment Failure, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Relevant Truck Floor, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved

SUPPRESSION REPAIR, 09/08/18
Div D/E

SoCal IMT 3 GIS
September 07, 2018
1951

QR Code

Miles
0 0.25 0.5 1

Datum: NAD 83

SOUTHERN CALIFORNIA
FIRE AUTHORITY

FOREST SERVICE
U.S. DEPARTMENT OF AGRICULTURE

INTERAGENCY INCIDENT MANAGEMENT

Mendocino Complex

CA-MEU-008674
September 8, 2018

SUPPRESSION REPAIR

Div D/E

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- Other State Lands
- USDA Forest Service

Other Symbols

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area

Road Class shown in fuchsia. Not all roads show Road Class values