



- Suppression Repair Points**
- PointType, Repair Status
 - Edge, Repair Needed
 - Chipping Blows, Repair Needed
 - Chipping Blows, Completed - Approved
 - Covert Damage, Repair Needed
 - Covert Damage, Completed - Approved
 - Clear Pines, Repair Needed
 - Clear Pines, Completed - Approved
 - Drop Pines, Repair Needed
 - Drop Pines, Completed - Approved
 - Equipment Faults, Repair Needed
 - Equipment Faults, Completed - Approved
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Trees, Repair Needed
 - Hazard Trees, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Track Floor, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing - Health
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Waterstar Needed, Repair Needed
 - Waterstar Needed, Completed - Approved

MNE MUST APPROVE BEFORE REPAIRING

Road Class shown in fuschia. Not all roads show Road Class values

SUPPRESSION REPAIR_09/08/18
Div L

SoCal IMT 3 GIS
September 07, 2018

QR Code

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex

CA-MEU-008674
September 8, 2018

SUPPRESSION REPAIR

Div L

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands
- Other Symbols**
- Uncontrolled Fire Edge
 - Contained Fire Edge
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area