

SUPPRESSION REPAIR, 09/18/18
Div F/G

N
W E
S

SoCal IMT 3 GIS
September 17, 2018
2259

QR Code

Miles
0 0.25 0.5 1

Datum: NAD 83

Interagency Incident Management Team
Nor Cal 1

Mendocino Complex

CA-MEU-008674

September 18, 2018

SUPPRESSION REPAIR
Div F/G

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)

- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area

Ownership

- USDA Forest Service

SUPPRESSION REPAIR, 09/18/18
Div F/G