



- Suppression Repair Points**
 PointType, Repair Status
- Ridge Repair Needed - Approved
 - Chipping Blank Repair Needed - Approved
 - Culvert Damage, Repair Needed - Approved
 - Clear Patch, Repair Needed - Approved
 - Clear Patch, Completed - Approved
 - Drop Point, Repair Needed - Approved
 - Equipment Piling, Repair Needed - Approved
 - Fence Damage, Repair Needed - Approved
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed - Approved
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed - Approved
 - Helicopter, Repair Needed - Approved
 - Log and Scatter Trees, Repair Needed - Approved
 - Machine Damage, Repair Needed - Approved
 - Other, Repair Needed - Approved
 - Other, Completed - Approved
 - Reservoir Truck Piling, Repair Needed - Approved
 - Road Needs Repair, Repair Needed - Approved
 - Road Needs Repair, Completed - Approved
 - Water Course Closing - Repair Needed - Approved
 - Water Course Closing - Repair Needed - Approved
 - Water Course Closing, Completed - Approved
 - Water Checking Location, Repair Needed - Approved
 - Waterbar Needed, Repair Needed - Approved
 - Waterbar Needed, Completed - Approved

Mendocino Complex
 CA-MEU-008674
 September 18, 2018
SUPPRESSION REPAIR
 Div I

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands
- Other Symbols:**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Direct Protection Areas
 - Rehab Avoidance Area

SUPPRESSION REPAIR, 09/18/18
 Div I

N
 W E
 S

QR Code

Miles
 0 0.25 0.5 1

Datum: NAD 83

SoCal IMT 3 GIS
 September 17, 2018
 2305

