




SUPPRESSION REPAIR, 09/18/18
Div J

























 SoCal IMT 3 GIS
 September 17, 2018
 2307
 Datum: NAD 83



Mendocino Complex

CA-MEU-008674
September 18, 2018

SUPPRESSION REPAIR Div J

Repair Legend  Completed - Inspected  Completed - Ready for Inspection  In Progress  No Repair Needed  Other - See Comments  Repair Needed  Unknown	 Completed Dozer Line  Completed Hand Line  Road as Completed Line	 Direct Protection Areas  Wilderness Area  Rehab Avoidance Area	Ownership  Other State Lands  USDA Forest Service  Bureau of Reclamation  Bureau of Land Management  Other Federal Lands
--	---	--	---

SUPPRESSION REPAIR, 09/18/18
Div J