



- Suppression Repair Points**
- Point Type, Repair Status
 - Ridge, Repair Needed
 - Chopping Blows, Repair Needed
 - Clearcut Damage, Repair Needed - Approved
 - Clearcut Damage, Completed - Approved
 - Clear Flush, Repair Needed
 - Clear Flush, Completed - Approved
 - Drop Piles, Repair Needed
 - Equipment Piles, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Helispot, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Recreation Truck Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Water Crossing Location, Completed - Approved
 - Waterbar Needs Repair, Repair Needed
 - Waterbar Needs Repair, Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class values

Mendocino Complex
 CA-MEU-008674
 September 19, 2018
SUPPRESSION REPAIR
 Div H

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
 - USDA Forest Service

SUPPRESSION REPAIR, 09/19/18
 Div H

QR Code

Miles

0 0.25 0.5 1

Datum: NAD 83

Interagency Incident Management Team
 Nor Cal 1

NorCal IMT 1 GIS
 September 18, 2018
 2229

SUPPRESSION REPAIR, 09/19/18
 Div H

SUPPRESSION REPAIR, 09/19/18
 Div H