



- Suppression Repair Points**
- PointType, Repair Status
 - Ridge Repair Needed
 - Chopping Blows Repair Needed
 - Chopping Blows Completed - Approved
 - Covert Damage Repair Needed
 - Covert Damage Completed - Approved
 - Clear Push Repair Needed
 - Clear Push Completed - Approved
 - Drop Point Repair Needed
 - Drop Point Completed - Approved
 - Equipment Ponds Repair Needed
 - Fence Damage Repair Needed
 - Fence Damage Completed - Approved
 - Gate Repair Needed
 - Gate Completed - Approved
 - Hazard Tree Repair Needed
 - Hazard Tree Repair Approved
 - Helicopter Repair Needed
 - Log and Scatter Trees Repair Needed
 - Machine Damage Repair Needed
 - Machine Damage Completed - Approved
 - Other Repair Needed
 - Other Repair Approved
 - Rebarbed Track Floor Repair Needed
 - Road Needs Repair Repair Needed
 - Road Needs Repair Completed - Approved
 - Water Course Closing - Health
 - Water Course Closing Repair Needed
 - Water Course Closing Completed - Approved
 - Water Ditching Location Repair Needed
 - Water Ditching Location Completed - Approved
 - Waterbar Repair Repair Needed
 - Waterbar Repair Completed - Approved

Mendocino Complex
 CA-MEU-008674
 September 19, 2018
SUPPRESSION REPAIR
 Div J

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Other Federal Lands
- Other Symbols:**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area

SUPPRESSION REPAIR, 09/19/18 Div J

NorCal IMT 1 GIS
September 18, 2018
2517

Miles
0 0.25 0.5 1

Datum: NAD 83

SUPPRESSION REPAIR, 09/19/18 Div J

Road Class shown in fuchsia. Not all roads show Road Class value.