


- Suppression Repair Points**
- PointType: Repair Status
  - Chipping Blows: Repair Needed
  - Chipping Blows: Completed - Approved
  - Covert Damage: Repair Needed
  - Covert Damage: Completed - Approved
  - Clear Pileup: Repair Needed
  - Clear Pileup: Completed - Approved
  - Drop Pileup: Repair Needed
  - Drop Pileup: Completed - Approved
  - Equipment Failure: Repair Needed
  - Equipment Failure: Completed - Approved
  - Force Damage: Repair Needed
  - Force Damage: Completed - Approved
  - Gate: Repair Needed
  - Gate: Completed - Approved
  - Hazard Tree: Repair Needed
  - Hazard Tree: Completed - Approved
  - Helicopter: Repair Needed
  - Helicopter: Completed - Approved
  - Log and Scatter Trees: Repair Needed
  - Log and Scatter Trees: Completed - Approved
  - Mechanical Damage: Repair Needed
  - Mechanical Damage: Completed - Approved
  - Other: Repair Needed
  - Other: Completed - Approved
  - Rehabilitate Truck Point: Repair Needed
  - Rehabilitate Truck Point: Completed - Approved
  - Road Needs Repair: Repair Needed
  - Road Needs Repair: Completed - Approved
  - Water Course Crossing: Repair Needed
  - Water Course Crossing: Completed - Approved
  - Water Course Crossing: Repair Needed
  - Water Course Crossing: Completed - Approved
  - Water Drafting Location: Repair Needed
  - Water Drafting Location: Completed - Approved
  - Waterbar Needed: Repair Needed
  - Waterbar Needed: Completed - Approved
  - Waterbar Needed: Repair Needed
  - Waterbar Needed: Completed - Approved

STATE DPA  
FEDERAL DPA

SUPPRESSION REPAIR, 09/2018  
Div F/G



Miles  
0 0.25 0.5 1

NorCal IMT 1 GIS  
September 19, 2018  
2223

Datum: NAD 83



# Mendocino Complex

CA-MEU-008674  
September 20, 2018

## SUPPRESSION REPAIR

### Div F/G

**Repair Legend**

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)

- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area

**Ownership**

- USDA Forest Service

SUPPRESSION REPAIR, 09/2018  
Div F/G

Road Class shown in fuchsia. Not all roads show Road Class values