


- Suppression Repair Points**
- PointType, Repair Status
- Ridge, Repair Needed
 - Chipping Blows, Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Path, Repair Needed
 - Clear Path, Completed - Approved
 - Drop Point, Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Ponds, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Harvest Tree, Repair Needed
 - Helicopter, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Muckout Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Retention Truck Ponds, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Waterbar, Repair Needed
 - Waterbar, Completed - Approved



SUPPRESSION REPAIR, 09/2018
Div K

Scale: 0, 0.25, 0.5, 1 Miles

Datum: NAD 83

NorCal IMT 1 GIS
September 19, 2018
2159



Mendocino Complex

CA-MEU-008674
September 20, 2018

SUPPRESSION REPAIR

Div K

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Other Symbols**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands
- Other Legend**
- Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area

SUPPRESSION REPAIR, 09/2018
Div K

SUPPRESSION REPAIR, 09/2018
Div K