

Suppression Repair Status

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Branch I

Branch II

Ranch

Mendocino Complex
 CA-MEU-008674
 September 21, 2018
SUPPRESSION REPAIR
 Branch I & II

Other State Lands	Bureau of Land Management	Division Break	Helispot	Completed Dozer Line
USDA Forest Service	Bureau of Indian Affairs	Branch Break	Incident Command Post	Completed Hand Line
Bureau of Reclamation	Department of Defense	Mobile Weather Unit	Pump	Road as Completed Line
County Boundary	Other Federal Lands	Repeater	Water Source	Highways
Direct Protection Areas	Wilderness Area	Dip Site	Drop Point	Major Roads
Rehab Avoidance Area				Local Streets

SUPPRESSION REPAIR, 09/21/18
 Branch I & II

QR Code

Miles
 0 1/4 1/2 1

Datum: NAD 83

NorCal IMT1 GIS
 September 20, 2018
 2011

