




- Suppression Repair Points**
- Point Type, Repair Status
  - Bridge Repair Needed
  - Chequing Basin Repair Needed
  - Covert Damage, Completed - Approved
  - Covert Damage, Repair Needed
  - Crosswalk Repair Needed
  - Deer Park, Completed - Approved
  - Drop Point, Repair Needed
  - Equipment Fording Repair Needed
  - Face Damage, Repair Needed
  - Face Damage, Completed - Approved
  - Fence Repair Needed
  - Fence, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hilltop Repair Needed
  - Log and Skidder Tracks, Repair Needed
  - Masthead Damage, Repair Needed
  - Other - R&H
  - Other, Repair Needed
  - Other, Completed - Approved
  - Reforestation Track Plot, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Closing - R&H
  - Water Course Closing, Repair Needed
  - Water Course Closing, Completed - Approved
  - Water Choking Location, Repair Needed
  - Water Needed, Repair Needed
  - Water Needed, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values



Datum: NAD 83



**Mendocino Complex**  
CA-MEU-008674  
September 21, 2018  
**SUPPRESSION REPAIR**  
Div I

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line

- Direct Protection Areas
- Rehab Avoidance Area

- Ownership**
- USDA Forest Service
  - Bureau of Reclamation
  - Bureau of Land Management
  - Bureau of Indian Affairs
  - Other Federal Lands