



- Suppression Repair Points**
- PointType, Repair Status
- Bridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Chipping Blank, Completed - Approved
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Drop Pile, Repair Needed
 - Equipment Front, Repair Needed
 - Fence Change, Repair Needed
 - Fence Change, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Lap and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other - Chub
 - Other - Repair Needed
 - Other - Completed - Approved
 - Roadside Truck Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Road Needs Repair, Repair Needed
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Waterbar Needs Repair, Repair Needed
 - Waterbar Needs Repair, Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/23/18
Div H

QR Code

NorCal IMT 1 GIS
September 22, 2018
2131

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 23, 2018
SUPPRESSION REPAIR
Div H

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- USDA Forest Service
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
- Other Symbols**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w weight limit)

SUPPRESSION REPAIR, 09/23/18
Div H

SUPPRESSION REPAIR, 09/23/18
Div H