



**Suppression Repair Points**

PointType, Repair Status

- Ridge, Repair Needed
- Chipping Blows, Repair Needed
- Culvert Damage, Completed - Approved
- Culvert Damage, Repair Needed
- Clear Push, Repair Needed
- Clear Push, Completed - Approved
- Drop Point, Repair Needed
- Equipment Failure, Repair Needed
- Fence Damage, Repair Needed
- Fence Damage, Completed - Approved
- Gate, Repair Needed
- Gate, Completed - Approved
- Hazard Tree, Repair Needed
- Hazard Tree, Repair Needed
- Log and Scatter Trees, Repair Needed
- Mastic Damage, Repair Needed
- Other, Repair Needed
- Other, Completed - Approved
- Restored Track Point, Repair Needed
- Road Needs Repair, Repair Needed
- Road Needs Repair, Completed - Approved
- Water Course Crossing, Repair Needed
- Water Course Crossing, Repair Needed
- Water Course Crossing, Completed - Approved
- Water Drafting Location, Repair Needed
- Water Needs Repair, Repair Needed
- Water Needs Repair, Completed - Approved

**Repair Legend**

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

**Ownership**

- Other State Lands
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Other Federal Lands

**Other Symbols**

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area

**Mendocino Complex**  
 CA-MEU-008674  
 September 25, 2018  
**SUPPRESSION REPAIR**  
 Div J

Datum: NAD 83

Miles  
 0 0.25 0.5 1

QR Code

NorCal IMT 1 GIS  
 September 23, 2018  
 2141

Mendocino National Forest logo

SUPPRESSION REPAIR, 09/25/18 Div J

SUPPRESSION REPAIR, 09/25/18 Div J