


- Suppression Repair Points**
- PointType: Repair Status
 - Chipping Blank: Repair Needed
 - Chipping Blank: Completed - Approved
 - Culvert Damage: Repair Needed
 - Culvert Damage: Completed - Approved
 - Clear Patch: Repair Needed
 - Clear Patch: Completed - Approved
 - Deep Pits: Repair Needed
 - Deep Pits: Completed - Approved
 - Equipment Failure: Repair Needed
 - Equipment Failure: Completed - Approved
 - Force Damage: Repair Needed
 - Force Damage: Completed - Approved
 - Gate: Repair Needed
 - Gate: Completed - Approved
 - Hazard Tree: Repair Needed
 - Hazard Tree: Completed - Approved
 - Helicopter: Repair Needed
 - Helicopter: Completed - Approved
 - Log and Skid Trail: Repair Needed
 - Log and Skid Trail: Completed - Approved
 - Mechanical Damage: Repair Needed
 - Mechanical Damage: Completed - Approved
 - Other: Repair Needed
 - Other: Completed - Approved
 - Rehabilitate Truck Pits: Repair Needed
 - Rehabilitate Truck Pits: Completed - Approved
 - Road Needs Repair: Repair Needed
 - Road Needs Repair: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

Mendocino Complex
 CA-MEU-008674
 September 25, 2018
SUPPRESSION REPAIR
 Div F/G

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
 - USDA Forest Service

N
W E
S

QR Code

Miles
0 0.25 0.5 1

NorCal IMT 1 GIS
September 23, 2018
2156

Datum: NAD 83



SUPPRESSION REPAIR, 09/25/18
Div F/G

SUPPRESSION REPAIR, 09/25/18
Div F/G