



- Suppression Repair Points**
- PointType, Repair Status
  - Ridge, Repair Needed
  - Chipping Blank, Repair Needed
  - Culvert Damage, Repair Needed - Approved
  - Culvert Damage, Completed - Approved
  - Clear Path, Repair Needed
  - Clear Path, Completed - Approved
  - Drop Point, Repair Needed
  - Equipment Paved, Repair Needed
  - Force Damage, Repair Needed
  - Force Damage, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hazard Tree, Repair Needed
  - Log and Scatter Trees, Repair Needed
  - Miscellaneous Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Resistant Truck Point, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Drilling Location, Repair Needed
  - Water Drilling Location, Repair Needed
  - Water Drilling Location, Completed - Approved
  - Water Drilling Location, Completed - Approved

**Suppression Repair, 09/25/18**  
Div K

Scale: 0, 0.25, 0.5, 1 Miles

Datum: NAD 83

QR Code

NorCal IMT 1 GIS  
September 23, 2018  
2137



**Mendocino Complex**  
CA-MEU-008674  
September 25, 2018  
**SUPPRESSION REPAIR**  
Div K

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown
- Other Symbols**
- Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Bridge (w weight limit)
- Ownership**
- Other State Lands
  - USDA Forest Service
  - Bureau of Reclamation
  - Bureau of Land Management
  - Bureau of Indian Affairs
  - Other Federal Lands
- Other Legend**
- Direct Protection Areas
  - Wilderness Area
  - Rehab Avoidance Area

Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/25/18  
Div K

SUPPRESSION REPAIR, 09/25/18  
Div K