



- Suppression Repair Points**
- PointType, Repair Status
 - Bridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Chipping Blank, Completed - Approved
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Deep Pile, Repair Needed
 - Equipment Fault, Repair Needed
 - Force Damage, Repair Needed
 - Force Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Mechan Damage, Repair Needed
 - Other, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Track Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Water Crossing Location, Repair Needed
 - Water Needs, Repair Needed
 - Water Needs, Completed - Approved

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands

Mendocino Complex
 CA-MEU-008674
 September 25, 2018
SUPPRESSION REPAIR
 Div L

SUPPRESSION REPAIR, 09/25/18
 Div L

QR Code

NorCal IMT 1 GIS
 September 23, 2018
 2131

Miles
 0 0.25 0.5 1

Datum: NAD 83

