


PAGE REFERENCE

BRANCH 11 N
BRANCH 11 S
BRANCH 7 S & 5 N
BRANCH 7 S & 5 N
BRANCH 3



0 0.5 1 2
Miles
1:36,000
N
W E
S
Contour Interval = 40 ft

REPAIR MAP
August West
October 14, 2020
CAL FIRE GIS
10/13/2020
1749 Hours
NAD 83 Teale Albers

Repair Status Point

- Completed - Ready for Inspection
- Repair Needed
- Unknown

Infrastructure

- Bridge
- Culvert Damage
- Dozer Push
- Fence Damage
- Hazard Tree
- Other
- Road Needs Repair
- Safety Zone
- Water Course Crossing
- Waterbar Needed
- Gate

FSR BRANCH 7 S & 5 N

- Wilderness
- Federal DPA
- Local DPA
- Non-Profit Conservancies and Trusts
- Other State Lands
- USA Forest Service
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands

REPAIR MAP
August West
October 14, 2020
CA MEU 10843
October 14, 2020

REPAIR MAP
August West
October 14, 2020
FSR BRANCH 7 S & 5 N