

River Complex Rehabilitation Briefing

Rehabilitation as of
10/26/15 @ 1045 hrs

10/27/2015 Day




Legend

- ◆ Chipping
- * Culvert
- Drop Point
- ⊠ Erosion Potential
- Fence
- ▲ Hazard Tree
- ⊙ Helispot
- ⊕ Pump Site
- ⊕ Retardant/Mud Pit
- ✦ Road Repair
- ✦ Road Sign
- ▲ Safety Zone
- ⊙ Spike Camp
- ⊙ Staging Area
- ⊕ Stream Crossing
- ⊕ Water Source
- Chipping
- ⊗ Dozer Lines
- - - - Hand Line
- ◇◇◇◇ Retardant
- Road Repairs
- ▭ Fire Perimeter

Status Summary

- Undetermined
- Repair Needed
- Stage 1 Complete
- Stage 1 Verified
- Stage 2 Complete
- Stage 2 Verified
- No Repair Needed



0 1 2 Miles



Mark Nebel GISS
Heidi Esh GISS(I)
Monday, October 26, 2015, 1356 hrs

