


Div S (Branch II)





















Suppression Repair - Barker

Fork Complex
CA-SHF 002067
8/21/2015 1500



SUPPRESSION REPAIR

	Drop Point		Highway		Unknown		Completed Line
	Fire Location		Primary		Identified for Repair		Dozer Line
	Fire Location - Out		Secondary		In Progress		Handline
	Restricted Water Source		Jeep Trail		Repaired		
			SPI Gates		Repaired & READ Approved		
					Identified - No Repair		

