



# Repair Status

Fork Complex  
 CA-SHF 002067  
 9/06/2015  
 36,499 Acres



	Division		Mobile Weather Unit		Highway		County Road 330		County Line		Wilderness Area		USDA Forest Service		NON-FS		Unknown		Identified for Repair		Barrier
	Water Source		Repeater		Paved		West Exit		USDA Forest Service		Identified for Repair		In Progress		Identified for Repair		In Progress		Identified - No Repair Required		Identified for Repair
	Dip Site		Restricted Water Source		Primary		Buried Water Line - No Equipment		USDA Forest Service		In Progress		Identified - No Repair Required		Identified for Repair		In Progress		Identified - No Repair Required		Identified for Repair
	Helispot		Staging Area		Secondary		Salt Gulch Bypass		NON-FS		Repaired Completed		Identified - No Repair Required		Identified for Repair		Identified - No Repair Required		Identified - No Repair Required		Identified for Repair
	Incident Command Post		Road Closure		Jeep Trail		PGE_pipelines		Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required
			Pump		SPI Gates						Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required		Identified - No Repair Required

