

Suppression Repair- Peak

Fork Complex
CA-SHF 002067
9/18/2015

Status Update





Status

- Helispot, Repaired
- Barrier, Repaired
- Drop Point, Identified for Repair
- Drop Point, Repaired
- Drop Point, Identified- No Repair Required
- Repair Culvert, Identified for Repair
- Repair Dam, Identified for Repair
- Repair Fence, Identified for Repair
- ▲ Safety Zone, Identified for Repair
- ▲ Safety Zone, Repaired

Status

- Unknown
- Identified for Repair
- In Progress
- Repair Completed
- Identified- No Repair Required



JPG
September 17, 2015
2025 Hours

Deer