

# Suppression Repair-Shield

Fork Complex  
CA-SHF 002067  
9/18/2015

## Status Update





### Status

- Helispot, Repaired
- Barrier, Repaired
- Drop Point, Identified for Repair
- Drop Point, Repaired
- Drop Point, Identified- No Repair Required
- Repair Culvert, Identified for Repair
- Repair Dam, Identified for Repair
- Repair Fence, Identified for Repair
- ▲ Safety Zone, Identified for Repair
- ▲ Safety Zone, Repaired

### Status

- Unknown
- Identified for Repair
- In Progress
- Repair Completed
- Identified- No Repair Required



JPG  
September 17, 2015  
2025 Hours