



MAP 4

JPG
September 11, 2015
0706 Hours

OPERATIONS

Repair Status
Fork Complex
CA-SHF 002067
9/11/2015
36,499 Acres



(X) Division	ICP Staging	Highway	County Road 330	County Line	Repair Status	Repair Status	Drop Point, Identified for Repair
(W) Water Source	Mobile Weather Unit	Paved	West Exit	Wilderness Area	Unknown	Drop Point, In Progress	Repair Culvert, Identified for Repair
(D) Dip Site	Repeater	Primary	Buried Water Line - No Equipment	USDA Forest Service	Identified for Repair	Helispot, Repaired	Repair Dam, Identified for Repair
(H) Helispot	Restricted Water Source	Secondary	Salt Gulch Bypass	NON-FS	In Progress	Barrier, Repaired	Repair Fence, Identified for Repair
	Staging Area	Jeep Trail	PGE Pipelines		Repair Completed	Drop Point, Identified for Repair	Safety Zone, Identified for Repair
	Road Closure	SPI Gates			Identified- No Repair Required	Drop Point, Identified- No Repair Required	Safety Zone, Repaired
	Pump						

