

# Suppression Repair Map

**Repair Status**

- Unknown
- Identified for Repair
- In Progress
- Repaired
- Repaired & READ Approved
- Identified - No Repair

**Line Styles**

- < all other values >
- Unknown
- Identified for Repair
- In Progress
- Repaired
- Repaired & READ Approved
- Identified - No Repair
- Line ID Breaks
- Completed Dozer Line
- H - H - H Hand Line
- Completed Line
- Proposed Contingency Lines

- Fire Perimeter
- Transmission Line
- Ranger District Boundary
- Coho Critical Habitat
- Wild and Scenic River
- NestGroves\_Burnt\_Ranch\_03052015
- Wildlife Habitat
- Invented Roadless Area
- InvasivePlantCurrent
- TES Occurrences

