



0 0.5 1 Miles

Datum: NAD 1983

Legend	
	Visual Closure
	Disturbance Area
	Chipping Slash
	Culvert Damage
	Dozer Push
	Meadow Damage
	Other
	Road Needs Repair
	Water Course Crossing
	Water Drafting Location
	Completed - READ Approved
	Completed - Ready for READ Inspection
	Do Not Repair
	Identified for Repair
	In Progress
	Water Line
	USFS Trails
	Buried Power Line
	Private Property
	Division
	Mine_Hazard
	Drop Point
	Helispot
	Mobile Weather Unit
	Pump
	Safety Zone
	Water Source
	Uncontrolled Fire Edge
	Completed Dozer Line
	Completed Line
	Hand Line
	Road as Completed Line
	USFS_Roads

