



Suppression Repair
Delta - Hirz Fire
 CA-SHF-001444 - CA-SHF-001223
Hirz North
 10/8/2018



- Repair Status Line**
- Repair Needed
 - Completed - Inspected
 - Completed - Ready for Inspection
- Other Symbols**
- Completed Line
 - Completed Dozer Line
 - H H H Completed Hand Line
 - R R R Road as Completed Line
 - Other/Road
 - Slash Piles Along Roads
 - Repair Group Division Lines
 - National Forest Lands
 - Ranger District
 - Mountain Peaks

1:24,000