



Suppression Repair

Suppression Repair Zone Map

CA-PNF-001324
Walker Fire
Div F & G
09/17/2019

	Road Repair		Repeater		Other		Completed Dozer Line		Completed Hand Line		Repair Needed		Completed - Inspected
	Dozer Push		Retardant Mud Pit		Zone Break		Uncontrolled Fire Edge		Road as Completed Line		In Progress		Unknown
	Dip Site		Safety Zone		Division Break		Completed Line		Planned Fire Line		Other - See Comments		No Repair Needed
	Drop Point		Water Source		Repair by Hand								
	Hotspot		Repair Point										

Div A, C & E

Div Q, V & X

Div I, K & M

Div F & G

N

0 1 Miles