



Suppression Repair

Suppression Repair

Zone Map

CA-PNF-001324
Walker Fire
Div I, K & M
09/17/2019

	Stream Crossing		Helipoint		Other		Completed Dozer Line		Repair Needed		Completed - Inspected
	Dozer Push		Repeater		Zone Break		Uncontrolled Fire Edge		In Progress		Unknown
	Camp		Safety Zone		Division Break		Completed Line		Other - See Comments		No Repair Needed
	Dip Site		Water Source		Branch Break				Repair by Hand		
	Drop Point		Repair Point								

Div A, C & E

Div F & G

Div I, K & M

Div Q, V & X

0 1 Miles

N