





Walker Fire
CA-PNF-001324
09/26/2019

	Total Miles	% Completed & Inspected
Dozer Line	75.0	27%
Hand Line	14.0	100%
Road	61.6	73%

West Repair

East Repair



● Repair Needed	H-H-H Completed Hand Line
● In Progress	R-R-R Road as Completed Line
● Completed - Ready for Inspection	— Completed Line
● Completed - Inspected	— Access or Improved Road
XXXXX Completed Dozer Line	— Repair Line
○ Other	■ Walker Mine
 Exclusion Zone	