




Walker Fire
CA-PNF-001324
09/29/2019

Suppression Repair Progress		
	Total Miles	% Completed & Inspected
Dozer Line	76.0	32%
Hand Line	14.0	100%
Road	72.0	61%

West Repair

East Repair



North arrow pointing up.

Scale bar: 0 1/2 1 2 3 4 5 Miles

- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Special Treatment Area
- XXXXX Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Completed Line
- Access or Improved Road
- Repair Line
- Other
- Walker Mine
- ▨ Exclusion Zone