

Suppression Repair Progress

Walker Fire

CA-PNF-001324

10/01/2019





Last Updated 09/29/2019

	Total Miles	% Completed & Inspected
Dozer Line	76.0	32%
Hand Line	14.0	100%
Road	72.0	61%

West Repair

East Repair



- Repair Needed
- - - Completed Hand Line
- In Progress
- - - Road as Completed Line
- Completed - Ready for Inspection
- Completed Line
- Completed - Inspected
- Access or Improved Road
- Special Treatment
- Repair Line
- XXXXX Completed Dozer Line
- Other
- Walker Mine
- ▨ Exclusion Zone

