


Road Repair Assessment

Walker Fire
CA-PNF-001324
October 01, 2019



Repair Status	
	Repair Needed
	In Progress
	Completed - Ready for Inspection
	Completed - Inspected
	No Repair Needed

Road Assessment Standard	
	Decommissioned
	ML 1 - Closed
	ML 2 - High Clearance
	ML 3 - Passenger Car
	ML 5 - High Level of Comfort
	County Road

Other Symbols	
	Culvert
	Dip Site
	Drop Point
	Dozer Push
	Hazard
	Helispot
	Repair Point
	Road Repair
	Safety Zone
	Stream Crossing
	Water Source
	Value at Risk
	Zone Break
	Division Break
	Completed Hand Line
	Road as Completed Line
	Completed Dozer Line
	Fence - Cut/Damaged

