


WEST REPAIR

EAST REPAIR

Access or Improved Road Repair Status	Length Miles
Completed - Inspected	19.98
Completed - Ready for Inspection	36.87
In Progress	7.46
No Repair Needed	98.33
Repair Needed	30.35
<Null>	0.68
Grand Total	193.67



● Drop Point
● Helispot
X Division Break
--- Completed Dozer Line
- - - Road as Completed Line

Repair Status

- Red: Repair Needed
- Yellow: In Progress
- Orange: Completed - Ready for Inspection
- Green: Completed - Inspected
- Purple: No Repair Needed