


IR Perimeter
9/23/2019
@1952 hrs



Suppression Repair
Middle Fire
1,339 Acres
CA-SHF-001196
9/24/2019

Repair Status	Symbol/Color	Land Ownership	Symbol/Color	Transportation
Completed - Inspected / No Repair Needed	Green line	Non-FS	Red dashed line	Completed Line
Completed - No Repair Needed	Yellow line	USDA Forest Service	Red solid line	Completed Hand Line
Completed - Ready for Inspection	Yellow dashed line	Wilderness Boundary	Red dashed line with triangles	Local Road
Completed - Ready for Inspection	Yellow solid line		Red dashed line with circles	Road as Completed Line
In Progress	Orange line		Red dashed line with squares	Trail
Repair Needed / Unknown	Red line		Red dashed line with diamonds	
Drop Point	Black circle		Red dashed line with crosses	
Hellspot	Blue circle		Red dashed line with stars	
Sling Site	Blue triangle		Red dashed line with triangles	
Water Source	Blue circle with 'W'		Red dashed line with circles	
In Progress	Orange line		Red dashed line with squares	
Repair Needed / Unknown	Red line		Red dashed line with diamonds	
Uncontrolled Fire Edge	Red dashed line		Red dashed line with crosses	
Wildfire Daily Fire Perimeter	Red solid line		Red dashed line with stars	
Fire History	Grey shaded area		Red dashed line with triangles	
Completed Hand Line	Black dashed line		Red dashed line with circles	
Road as Completed Line	Black dashed line with 'R-R'		Red dashed line with squares	
Trail	Black dashed line with 'X'		Red dashed line with diamonds	

