



















 Contained Line
 Completed Dozer Line
 Completed Hand Line
 No Repair Needed
 Repair Needed
 County Boundary
Ownership
 National Park Service
 USDA Forest Service
 Bureau of Land Management






-  Dip Site
-  Contained Line
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service














**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 3 of 20**

-  Contained Line
-  Railroads
-  Transmission Lines
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service
-  Bureau of Land Management






**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 4 of 20**

-  Dip Site
-  Railroads
-  Pipeline
-  Transmission Lines
-  Repair Needed
-  County Boundary
- Ownership**
-  USDA Forest Service
-  Bureau of Land Management















**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 5 of 20**

-  Culvert
-  Fence - Cut/Damaged
-  Other
-  Contained Line
-  Completed Dozer Line
-  H - H Completed Hand Line
-  R - R Road as Completed Line
-  Repair Needed
-  No Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service















**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 6 of 20**

-  Other
-  Contained Line
-  Completed Dozer Line
- R - R** Road as Completed Line
-  Repair Needed
-  No Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service






**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 7 of 20**







-  Contained Line
-  Completed Dozer Line
-  Railroads
-  Transmission Lines
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service
-  Bureau of Land Management






JAD
8/1/2020
9:04:10 PM













- Contained Line
- XXXXX Completed Dozer Line
- H - H Completed Hand Line
- Railroads
- Pipeline
- Transmission Lines
- No Repair Needed
- Repair Needed
- County Boundary
- Ownership**
- USDA Forest Service
- Bureau of Land Management






-  Other
-  Contained Line
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service



















**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 10 of 20**

-  Drop Point
-  Hazard Tree
-  Safety Zone
-  Other
-  Contained Line
-  Completed Dozer Line
-  Repair Needed
-  No Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service




















**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 11 of 20**















-  Safety Zone
-  Contained Line
-  Completed Dozer Line
-  H - H Completed Hand Line
-  R - R Road as Completed Line
-  Railroads
-  Transmission Lines
-  Repair Needed
-  No Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service






Div Y
DM Z











-  Dip Site
-  Safety Zone
-  Contained Line
-  Completed Dozer Line
-  H - H Completed Hand Line
-  R - R Road as Completed Line
-  Railroads
-  Pipeline
-  Transmission Lines
-  Repair Needed
-  No Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  USDA Forest Service








-  Drop Point
-  Hazard Tree
-  Safety Zone
-  Other
-  Uncontrolled Fire Edge
-  Contained Line
-  Completed Dozer Line
-  Completed Hand Line
-  Railroads
-  Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service



**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 14 of 20**

-  Drop Point
-  Hazard Tree
-  Hot Spot
-  Safety Zone
-  Other
-  Uncontrolled Fire Edge
-  Contained Line
-  Completed Dozer Line
-  Completed Hand Line
-  Railroads

-  Repair Needed
 -  No Repair Needed
 -  Repair Needed
 -  County Boundary
- Ownership**
-  National Park Service
 -  USDA Forest Service



MODOC COUNTY

SISKIYOU COUNTY

T45N R3E

T45N R4E

T45N R5E

T44N R3E















T44N R4E




T44N R5E

DP-8














DP-5




**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 15 of 20**













-  Drop Point
-  Hazard Tree
-  Safety Zone
-  Other
-  Contained Line
-  Completed Dozer Line
- R - R** Road as Completed Line
-  Railroads
-  Transmission Lines
-  Repair Needed
-  No Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  National Park Service
-  USDA Forest Service





**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 16 of 20**














-  Helispot
-  Safety Zone
-  Other
-  Contained Line
-  Completed Dozer Line
- R - R Road as Completed Line
-  Railroads
-  Pipeline
-  Transmission Lines
-  Repair Needed
-  No Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  USDA Forest Service




-  Drop Point
-  Other
-  Uncontrolled Fire Edge
-  Contained Line
-  Completed Dozer Line
-  H - H Completed Hand Line
-  R - R Road as Completed Line
-  Railroads
-  Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  USDA Forest Service



**July Complex
Repair Tiles
CA-MDF-000487
08/02/2020
Page 18 of 20**

-  Drop Point
-  Safety Zone
-  Other
-  Uncontrolled Fire Edge
-  Contained Line
-  Completed Dozer Line
-  H - H Completed Hand Line
-  R - R Road as Completed Line
-  Railroads
-  Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  USDA Forest Service





**CALIFORNIA
INCIDENT MANAGEMENT
TEAM 12**



TEAM 1




**NATIONAL
PARK
SERVICE**



















**FOREST SERVICE
U.S. DEPARTMENT OF AGRICULTURE**
















JAD
8/1/2020
9:07:58 PM



-  Dip Site
-  Drop Point
-  Contained Line
-  Completed Dozer Line
-  H - H Completed Hand Line
-  R - R Road as Completed Line
-  Other
-  Railroads
-  Transmission Lines
-  Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  USDA Forest Service



-  Safety Zone
-  Other
-  Contained Line
-  Completed Dozer Line
-  Completed Hand Line
-  Railroads
-  Pipeline
-  Transmission Lines
-  Repair Needed
-  Repair Needed
-  County Boundary
- Ownership**
-  USDA Forest Service

