


NW Repair Map
 August Complex Northwest Zone
 CA-MNF-000753
 10/12/2020



- | | | | | | | |
|---|--|---|---|---|---|---|
| <ul style="list-style-type: none"> ● Camp (2) ● Dip Site (8) ● Drop Point (39) ● Hazard (1) ● Helispot (8) ● Mobile Weather Unit (5) ● Repeater (6) ● Retardant/Mud Pit (1) | <ul style="list-style-type: none"> ● Road Repair (1) ● Staging Area (1) ● Water Source (10) ● Restricted Water Source (1) ● Value at Risk (6) ● Zone Break (3) ● Division Break (7) | <ul style="list-style-type: none"> □ Branch Break (2) □ Accountable Property □ Water Tank (4) □ Access or Improved Road (4) □ Completed Dozer Line (238) □ Completed Hand Line (25) | <ul style="list-style-type: none"> — Contained Line (20) — Fence (2) — Road as Completed Line (33) — Uncontrolled Fire Edge (39) ● Repair Needed (41) ● Repair Needed (189) ● No Repair Needed (2) — Zone Break | <ul style="list-style-type: none"> ● Bureau of Land Management ● Forest Service ● Roads Mendocino/NF — County — State/cnty/US roads — State — STATE — FEDERAL | <ul style="list-style-type: none"> — Repair Status Line — In Use - Fire Management — Completed - Ready for Inspection — In Progress — Repair Needed — No Repair Needed — Other - See Comments — Unknown | <ul style="list-style-type: none"> ● Repair Status Point ● Completed - Inspected ● In Use - Fire Management ● Completed - Ready for Inspection ● In Progress ● Repair Needed ● No Repair Needed ● Other - See Comments ● Unknown |
|---|--|---|---|---|---|---|