


NW Repair Map
 August Complex Northwest Zone
 CA-MNF-000753
 10/19/2020



- | | | | | | |
|--|---|--|--|--|---|
| <ul style="list-style-type: none"> ● Camp ● Dip Site ● Drop Point --- Gate ⚠ Hazard ⚠ Hazard Tree ● HeliSpot ⊙ Landing or Log Deck | <ul style="list-style-type: none"> ⊙ Mobile Weather Unit ⊙ Repeater ⊙ Retardant in Avoidance Area ⊙ Retardant/Mud Pit ⊙ Road Repair ⊙ Staging Area ⊙ Stream Crossing ⊙ Structure Wrap | <ul style="list-style-type: none"> ⊙ Water Source ⊙ Restricted Water Source ⊙ Value at Risk ⊙ Zone Break ⊙ Division Break ⊙ Branch Break ⊙ Pump | <ul style="list-style-type: none"> ⊙ Other Property ⊙ Water Tank ⊙ Access or Improved Road ⊙ Aerial Retardant Drop ⊙ Completed Dozer Line ⊙ Completed Hand Line ⊙ Contained Line ⊙ Fence | <ul style="list-style-type: none"> ● Completed - Inspected (1) ● Completed - Ready for Inspection (3) ● In Progress (2) ● Repair Needed (306) ● Unknown (14) ● Repair Needed (67) ● Unknown (1) | <ul style="list-style-type: none"> — State — Road — Forest — DPA — STATE — FEDERAL — Bureau of Land Management — Forest Service — Indian Reservation |
|--|---|--|--|--|---|