


NW Repair Map
 August Complex Northwest Zone
 CA-MNF-000753
 10/20/2020



- | | | | | | | |
|--|---|---|--|--|---|--|
| <ul style="list-style-type: none"> ● Camp ✕ Closure ● Dip Site ● Drop Point — Gate ⚠ Hazard ⚠ Hazard Tree ● Helispot | <ul style="list-style-type: none"> ● Hot Spot Ⓜ Landing or Log Deck Ⓜ Mobile Weather Unit Ⓜ Retardant in Avoidance Area Ⓜ Retardant/Mud Pit Ⓜ Road Repair Ⓜ Staging Area | <ul style="list-style-type: none"> Ⓜ Stream Crossing Ⓜ Structure Wrap Ⓜ Water Source Ⓜ Restricted Water Source Ⓜ Value at Risk Ⓜ Zone Break Ⓜ Division Break | <ul style="list-style-type: none"> Ⓜ Branch Break Ⓜ Pump Ⓜ Other Property Ⓜ Repeater Ⓜ Access or Improved Road Ⓜ Aerial Retardant Drop Ⓜ Completed Dozer Line | <ul style="list-style-type: none"> — Completed Hand Line — Contained Line — Fence — Repair Line — Road Repair — Road as Completed Line — Uncontrolled Fire Edge — Zone Break | <ul style="list-style-type: none"> ● Repair Needed (67) ● Unknown (1) ● Completed - Inspected (4) ● Completed - Ready for Inspection (13) ● In Progress (2) ● Repair Needed (301) ● No Repair Needed (1) ● Unknown (15) | <ul style="list-style-type: none"> ● Bureau of Land Management ● Forest Service ● Indian Reservation ● State ● Roads ● Forest ● DPA ● STATE ● FEDERAL |
|--|---|---|--|--|---|--|