


Repair Map
 NW/NE Zones August Complex
 CA-MNF-000753
 10/23/2020



- | | | | | | | |
|--|---|---|--|---|---|--|
| <ul style="list-style-type: none"> ✕ Closure ● Dip Site ● Drop Point ⊘ Gate ⚠ Hazard ⚠ Hazard Tree | <ul style="list-style-type: none"> ● Hot Spot ● Landing or Log Deck ● Mobile Weather Unit ● Repeater ● Retardant in Avoidance Area ● Retardant/Mud Pit ● Road Repair | <ul style="list-style-type: none"> ⊠ Stream Crossing ⊠ Structure Wrap ● Water Source ⊠ Restricted Water Source ● Value at Risk ● Zone Break | <ul style="list-style-type: none"> ⊠ Division Break ⊠ Branch Break ● Pump ● Other Property ● Water Tank ⊠ Access or Improved Road ⊠ Aerial Retardant Drop | <ul style="list-style-type: none"> ⊠ Completed Dozer Line ⊠ Contained Line ⊠ Fence ⊠ Repair Line ⊠ Road Repair ⊠ Road as Completed Line ⊠ Uncontrolled Fire Edge | <ul style="list-style-type: none"> ● Completed - Inspected (24) ● Completed - Ready for Inspection (12) ● In Progress (13) ● Repair Needed (285) ● No Repair Needed (1) ● Unknown (15) ● Zone Break ● Bureau of Land Management | <ul style="list-style-type: none"> ● Forest Service ● Indian Reservation ● State ● Forest ● DPA ● STATE ● FEDERAL |
|--|---|---|--|---|---|--|