



**Repair Map**  
 NW/NE Zones August Complex  
 CA-MNF-000753  
 10/24/2020



- |  |   |   |  |  |   |  |
|--|---|---|--|--|---|--|
| <ul style="list-style-type: none"> <li>✕ Closure</li> <li>● Dip Site</li> <li>● Drop Point</li> <li>⊘ Gate</li> <li>⚠ Hazard</li> <li>⚠ Hazard Tree</li> </ul> | <ul style="list-style-type: none"> <li>● Hot Spot</li> <li>● Landing or Log Deck</li> <li>● Mobile Weather Unit</li> <li>● Repeater</li> <li>● Retardant in Avoidance Area</li> <li>● Retardant/Mud Pit</li> <li>● Road Repair</li> </ul> | <ul style="list-style-type: none"> <li>⊠ Stream Crossing</li> <li>⊠ Structure Wrap</li> <li>● Water Source</li> <li>● Restricted Water Source</li> <li>● Value at Risk</li> <li>● Zone Break</li> </ul> | <ul style="list-style-type: none"> <li>⊠ Division Break</li> <li>⊠ Branch Break</li> <li>● Pump</li> <li>● Other Property</li> <li>● Water Tank</li> <li>⊠ Access or Improved Road</li> <li>◇ Aerial Retardant Drop</li> </ul> | <ul style="list-style-type: none"> <li>⊠ Completed Dozer Line</li> <li>⊠ Completed Hand Line</li> <li>⊠ Contained Line</li> <li>⊠ Fence</li> <li>⊠ Repair Line</li> <li>⊠ Road Repair</li> <li>⊠ Road as Completed Line</li> <li>⊠ Uncontrolled Fire Edge</li> </ul> | <ul style="list-style-type: none"> <li>● Completed - Inspected (24)</li> <li>● Completed - Ready for Inspection (12)</li> <li>● In Progress (13)</li> <li>● Repair Needed (286)</li> <li>● No Repair Needed (1)</li> <li>● Unknown (14)</li> <li>● Zone Break</li> <li>● Bureau of Land Management</li> </ul> | <ul style="list-style-type: none"> <li>● Forest Service</li> <li>● Indian Reservation</li> <li>● State</li> <li>● Forest</li> <li>● DPA</li> <li>● STATE</li> <li>● FEDERAL</li> </ul> |
|--|---|---|--|--|---|--|