


Repair Map
 August Complex
 CA-MNF-000753
 11/01/2020



- | | | | | | |
|--|--|--|--|---|--|
| <ul style="list-style-type: none"> ● Completed - Ready for Inspection ● In Progress ● No Repair Needed ● No Repair Needed ● Unknown ● Completed - Inspected ● In Use - Fire Management ● Completed - Ready for Inspection ● In Progress | <ul style="list-style-type: none"> ● No Repair Needed ● Other - See Comments ● Unknown ● Camp ● Closure ● Dip Site ● Drop Point | <ul style="list-style-type: none"> ● Gate ● Hazard ● Hazard Tree ● Hot Spot ● Internet Access ● Landing or Log Deck ● Mobile Weather Unit ● Repeater ● Retardant in Avoidance Area ● Retardant/Mud Pit ● Road Repair ● Staging Area ● Stream Crossing ● Structure Wrap ● Water Source | <ul style="list-style-type: none"> ● Restricted Water Source ● Value at Risk ● Zone Break ● Division Break ● Branch Break ● Contained Line ● Fence ● Repair Line | <ul style="list-style-type: none"> ● Water Tank ● Access or Improved Road ● Aerial Retardant Drop ● Completed Dozer Line ● Completed Hand Line ● Contained Line ● Water Tank ● Road Repair ● Road as Completed Line ● Uncontrolled Fire Edge ● Bureau of Land Management ● Forest Service ● Indian Reservation ● State ● FEDERAL | <ul style="list-style-type: none"> ● Roads ● Forest ● DPA ● STATE ● FEDERAL |
|--|--|--|--|---|--|