


**August Complex South Zone**  
 CA-MNF-000753  
**Incident Repair Status**  
 Delta 2  
 Operational Period 11/13/2020



- |  |   |   |   |   |  |  |   |   |
|--|---|---|---|---|--|--|---|---|
| <ul style="list-style-type: none"> <li>Zone Break</li> <li>Road Repair (1)</li> <li>Road as Completed Line (18)</li> <li>Completed Dozer Line (147)</li> </ul> | <ul style="list-style-type: none"> <li>Completed Hand Line (4)</li> <li>Completed - Inspected (27)</li> <li>Completed - Ready for Inspection (4)</li> <li>In Progress (14)</li> </ul> | <ul style="list-style-type: none"> <li>Repair Needed (120)</li> <li>No Repair Needed (4)</li> <li>Unknown (1)</li> <li>Repair Point (10)</li> </ul> | <ul style="list-style-type: none"> <li>Fence - Cut/Damaged (3)</li> <li>Hazard (3)</li> <li>Dozer Push (5)</li> <li>Value at Risk (14)</li> </ul> | <ul style="list-style-type: none"> <li>Drop Point (9)</li> <li>Gate (13)</li> <li>Helispot (4)</li> </ul> | <ul style="list-style-type: none"> <li>Completed - Inspected (3)</li> <li>In Progress (3)</li> <li>Repair Needed (16)</li> </ul> | <ul style="list-style-type: none"> <li>No Repair Needed (2)</li> <li>Other - See Comments (1)</li> <li>Unknown (19)</li> </ul> | <ul style="list-style-type: none"> <li>Ranger District</li> <li>Wilderness</li> <li>Wilderness</li> </ul> | <ul style="list-style-type: none"> <li>NON-FS</li> <li>USDA FOREST SERVICE</li> </ul> |
|--|---|---|---|---|--|--|---|---|

