



**August Complex South Zone**  
 CA-MNF-000753  
 Incident Repair Status

Operational Period 11/14/2020 NAD 1983 UTM Zone 10N

<ul style="list-style-type: none"> <li>— Zone Break</li> <li>X Division Break</li> <li>— Access or Improved Road (13)</li> <li>— Repair Line (22)</li> <li>— Road Repair (2)</li> <li>— Zone Break</li> <li>— Fence (1)</li> </ul>	<ul style="list-style-type: none"> <li>— Road as Completed Line (143)</li> <li>XX Completed Dozer Line (720)</li> <li>— Completed Hand Line (101)</li> <li>— Completed - Inspected (435)</li> </ul>	<ul style="list-style-type: none"> <li>— Completed - Ready for Inspection (7)</li> <li>— In Progress (65)</li> <li>— Repair Needed (347)</li> <li>— No Repair Needed (114)</li> </ul>	<ul style="list-style-type: none"> <li>— Other - See Comments (18)</li> <li>— Unknown (15)</li> <li>— Repair Point (118)</li> <li>— Fence - Cut/Damaged (16)</li> </ul>	<ul style="list-style-type: none"> <li>○ Culvert (53)</li> <li>⊗ Road Repair (3)</li> <li>⊗ Hazard (9)</li> <li>⊗ Clean Up Area (4)</li> </ul>	<ul style="list-style-type: none"> <li>⊗ Dozer Push (84)</li> <li>⊗ Stream Crossing (2)</li> <li>⊗ Value at Risk (83)</li> <li>⊗ Camp (4)</li> </ul>	<ul style="list-style-type: none"> <li>● Drop Point (70)</li> <li>⊗ Gate (17)</li> <li>⊗ Helipod (22)</li> <li>⊗ Restricted Water Source (1)</li> </ul>	<ul style="list-style-type: none"> <li>● Water Source (20)</li> <li>● Completed - Inspected (33)</li> <li>● No Repair Needed (11)</li> <li>● Unknown (114)</li> <li>● In Progress (12)</li> </ul>	<ul style="list-style-type: none"> <li>● Repair Needed (223)</li> <li>● Other - See Comments (2)</li> <li>● Wilderness</li> <li>● Wilderness</li> <li>● Non-FS</li> <li>● Ranger District</li> </ul>
--	---	---	---	--	--	---	---	--

Scale: 1:95,000

0 0.5 1 2 Miles  
 0 0.5 1 2 Kilometers

USDA FOREST SERVICE