


Repair Status South Zone

August Complex

CA-MNF-000753

4/24/2021



Current as of: 4/23/2021
NAID63 UTM 21UN



- | | | | | | |
|---|--|--|--|---|---|
| <ul style="list-style-type: none"> ● Aerial Hazard ● Dip Site ● Helispot ● Sling Site ● Division Break ● Drop Point ● Camp ● Value at Risk ● Other ● Landmark ● Gate | <ul style="list-style-type: none"> ● Bridge ● Structure Wrap ● Stream Crossing ● Road Repair ● Resource Location ● Restricted Water Source ● Hazard Tree ● Fence - Cut/Damaged ● Dozer Push ● Culvert ● Clean Up Area | <ul style="list-style-type: none"> ● Mobile Weather Unit ● Repeater ● Safety Zone ● Hazard ● Water Source ● Restricted Water Source ● Completed Dozer Line ● Completed Hand Line ● Planned Secondary Line ● Access or Improved Road ● Fence | <ul style="list-style-type: none"> ● Management Action Point ● Other ● Repair Line ● Road Repair ● Escape Route ● Contained Line ● Completed - Inspected (179) ● In Progress (22) ● Repair Needed (337) ● No Repair Needed (40) ● Other - See Comments (16) | <ul style="list-style-type: none"> ● Unknown (261) ● Completed - Inspected (567) ● Completed - Ready for Inspection (19) ● In Progress (69) ● Repair Needed (401) ● No Repair Needed (280) ● Other - See Comments (23) ● Unknown (187) ● Bureau of Land Management ● Forest Service ● Indian Reservation | <ul style="list-style-type: none"> ● State Roads ● 0 - Not Maintained ● 1 - Basic Custodial Care (CLOSED) ● 2 - 5 (OPEN) ● Private or County |
|---|--|--|--|---|---|