



Repair Status South Zone NE

August Complex

CA-MNF-000753

6/1/2021



Current as of: 6/1/2021
NADES UTM 210N



- | | | | | |
|---|---|---|---|--|
| <ul style="list-style-type: none"> ● Dip Site ● Helispot ● Sling Site ● Drop Point ● Closure ● Camp ● Staging Area ● Value at Risk ● Other ● Landmark ● Gate | <ul style="list-style-type: none"> ● Structure Wrap ● Stream Crossing ● Road Repair ● Repair Point ● Hazard Tree ● Fence - Cut/Damaged ● Dozer Push ● Culvert ● Mobile Weather Unit ● Repeater ● Safety Zone | <ul style="list-style-type: none"> ● Hazard ● Water Source ● Completed Dozer Line ● Completed Hand Line ● Access or Improved Road ● Repair Line ● Road Repair ● Road as Completed Line ● Completed - Inspected (111) ● Completed - Ready for Inspection (1) | <ul style="list-style-type: none"> ● In Progress (23) ● Repair Needed (121) ● No Repair Needed (62) ● Other - See Comments (17) ● Unknown (67) ● Completed - Inspected (362) ● Completed - Ready for Inspection (15) ● In Progress (96) ● Repair Needed (105) ● No Repair Needed (121) ● Other - See Comments (15) | <ul style="list-style-type: none"> ● Unknown (26) ● Bureau of Land Management ● Forest Service ● State <p>Roads</p> <ul style="list-style-type: none"> ○ Not Maintained ○ 1 - Basic Custodial Care (CLOSED) ○ 2 - 5 (OPEN) ○ Private or County |
|---|---|---|---|--|