



**Need Repair South Zone NE**  
**August Complex**  
**CA-MNF-000753**  
**6/1/2021**



Current as of: 6/1/2021  
 NAD83 UTM 12WN



- |  |   |  |  |  |
|--|---|--|--|--|
| <ul style="list-style-type: none"> <li>● Dip Site</li> <li>● Helipoint</li> <li>● Drop Point</li> <li>■ Closure</li> <li>■ Staging Area</li> <li>● Value at Risk</li> <li>● Other</li> <li>● Landmark</li> <li>● Gate</li> </ul> | <ul style="list-style-type: none"> <li>● Road Repair</li> <li>● Repair Point</li> <li>● Hazard Tree</li> <li>● Dozer Push</li> <li>● Culvert</li> <li>● Mobile Weather Unit</li> <li>● Repeater</li> <li>● Safety Zone</li> <li>● Hazard</li> </ul> | <ul style="list-style-type: none"> <li>● Water Source</li> <li>— Completed Dozer Line</li> <li>— Completed Hand Line</li> <li>— Access or Improved Road</li> <li>— Other</li> <li>— Road as Completed Line</li> <li>● Completed - Inspected (6)</li> <li>● In Progress (14)</li> <li>● Repair Needed (99)</li> </ul> | <ul style="list-style-type: none"> <li>● No Repair Needed (3)</li> <li>● Other - See Comments (15)</li> <li>● Unknown (33)</li> <li>— Completed - Ready for Inspection (12)</li> <li>— In Progress (19)</li> <li>— Repair Needed (34)</li> <li>— Other - See Comments (8)</li> <li>— Unknown (1)</li> <li>— Bureau of Land Management</li> </ul> | <ul style="list-style-type: none"> <li>■ Forest Service</li> <li>■ State</li> <li>■ Roads</li> <li>— 0 - Not Maintained</li> <li>— 1 - Basic Custodial Care (CLOSED)</li> <li>— 2 - 5 (OPEN)</li> <li>— Private or County</li> </ul> |
|--|---|--|--|--|