



Repair Status South Zone NE
 August Complex
 CA-MNF-000753
 6/6/2021



Current as of: 6/6/2021
 NAD83 UTM 12N



- | | | | | |
|---|---|--|---|--|
| <ul style="list-style-type: none"> ● Dip Site ● Helispot ● Sling Site ● Drop Point ● Closure ● Camp ● Staging Area ● Value at Risk ● Other ● Landmark ● Gate | <ul style="list-style-type: none"> ● Structure Wrap ● Stream Crossing ● Road Repair ● Repair Point ● Hazard Tree ● Fence - Cut/Damaged ● Dozer Push ● Culvert ● Clean Up Area ● Mobile Weather Unit ● Repeater | <ul style="list-style-type: none"> ▲ Safety Zone ▲ Hazard ● Water Source — Completed Dozer Line — Completed Hand Line — Access or Improved Road ● Other — Repair Line — Road Repair — Road as Completed Line ● Repeater | <ul style="list-style-type: none"> ● Completed - Ready for Inspection (7) ● In Progress (20) ● Repair Needed (65) ● No Repair Needed (75) ● Other - See Comments (35) ● Unknown (5) ● Completed - Inspected (386) ● Completed - Ready for Inspection (15) ● In Progress (94) ● Repair Needed (93) ● No Repair Needed (124) | <ul style="list-style-type: none"> — Other - See Comments (13) — Unknown (27) — Bureau of Land Management — Forest Service — State — Roads — 0 - Not Maintained — 1 - Basic Custodial Care (CLOSED) — 2 - 5 (OPEN) — Private or County |
|---|---|--|---|--|