



**Suppression Repair
North Complex**

**BRANCH V
SOUTHEAST**

October 12, 2020



- Division Break
- Aerial Hazard
- Bridge
- Camp
- Culvert
- Dip Site
- Dozer Push
- Drop Point
- Fence - Cut/Damaged
- Fire Station
- Gate
- Hazard
- Hazard Tree
- Helispot
- Incident Command Post
- Cell Service
- Landing or Log Deck
- Lookout
- Mobile Weather Unit
- Other
- Repair Point
- Repeater
- Retardant in Avoidance Area
- Safety Zone
- Staging Area
- Stream Crossing
- Structure Wrap
- Value at Risk
- Water Development or Draft Site
- Water Source
- SPI Gate
- MANDATORY EXCLUSION AREA
- Mine
- Structure
- SPI Fuelbreak
- Contained Line
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Access or Improved Road
- Completed Plow Line
- Aerial Retardant Drop
- Repair Line
- Road Repair
- Other
- Penstocks
- MANDATORY EXCLUSION AREA
- Historic Fire (1990-2019, 100+ acres)
- Road Class
- Roads Open to All Vehicles, Yearlong
- Roads Open to All Vehicles, Seasonal
- Roads Open to Highway Legal Vehicles Only, Yearlong
- Roads Open to Highway Legal Vehicles Only, Seasonal
- Special Vehicle Designation, Yearlong

Repair Status

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- In Use - Fire Management
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

MVUM Roads

Road Class

- Roads Open to All Vehicles, Yearlong
- Roads Open to All Vehicles, Seasonal
- Roads Open to Highway Legal Vehicles Only, Yearlong
- Roads Open to Highway Legal Vehicles Only, Seasonal
- Special Vehicle Designation, Yearlong

0 1/2 1 2 Miles