



Suppression Repair North Complex
BRANCH V
SOUTHWEST
 October 16, 2020



Zone Break	Drop Point	Other	Water Development or Draft Site	Completed Doser Line	Penstocks
Branch Break	Fence - Cut/Damaged	Repair Point	Water Source	Completed Hand Line	Agency Creek Special Interest Area
Division Break	Hazard	Repairer	GPS Gate	Road as Completed Line	Historic Fire (1990-2015, 100+ acres)
Bridge	Hazard Tree	Retardant in Avoidance Area	Mandatory Exclusion Area	Access or Improved Road	Road Class
Camp	Safety Zone	Safety Zone	Mine	Completed Prow Line	Roads Open to All Vehicles, Yearlong
Closure	Staging Area	Stream Crossing	Structure	Aerial Retardant Drop	Roads Open to All Vehicles, Seasonal
Dip Site	Landing or Log Deck	Locks	Contained Line	Ripper Line	Roads Open to Highway Legal Vehicles Only, Yearlong
Doser Push	Locks	Structure W/ing	Value at Risk	Road Repair	Roads Open to Highway Legal Vehicles Only, Seasonal
	Mobile Weather Unit			Other	Special Vehicle Designation, Yearlong

● Completed - Inspected	● Completed - Ready for Inspection	● In Progress
● No Repair Needed	● Repair Needed	● Other - See Comments
In Use - Fire Management		
MVUM Roads		
Road Class		
Roads Open to All Vehicles, Yearlong		
Roads Open to Highway Legal Vehicles Only, Yearlong		
Roads Open to Highway Legal Vehicles Only, Seasonal		
Special Vehicle Designation, Yearlong		

