



REPAIR - Event Point
Repair Status

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- In Use - Fire Management
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown
- Label_Point

Suppression Repair North Complex
 CA-PNF-001308
 October 16, 2020



- | | | | | | | |
|------------------|-------------------------|-----------------------|-------------------------------|-----------------------------------|-------------------------|----------------------------|
| • Zone Break | • Dozer Push | • Cell Service | • Restricted Water Source | • Value at Risk | • Completed Plow Line | • MANDATORY EXCLUSION AREA |
| • Aerial Hazard | • Drop Point | • Landing or Log Deck | • Retardant in Avoidance Area | • Water Development or Draft Site | • Active Burnout | • Mine |
| • Division Break | • Fence - Cut/Damaged | • Landmark | • Road Repair | • Water Source | • Completed Burnout | • Structure |
| • Branch Break | • Fire Station | • Lookout | • Safety Zone | • Uncontrolled Fire Edge | • Aerial Retardant Drop | • SPI Fuelbreak |
| • Bridge | • Gate | • Mobile Weather Unit | • Sling Site | • Contained Line | • Repair Line | • County Boundary |
| • Camp | • Hazard | • Other | • Spot Fire | • Completed Dozer Line | • Road Repair | • Fire Area |
| • Closure | • Hazard Tree | • Repair Point | • Staging Area | • Completed Hand Line | • Other | • MANDATORY EXCLUSION AREA |
| • Culvert | • Helispot | • Repeater | • Stream Crossing | • Road as Completed Line | • Other | • Label_Point |
| • Dip Site | • Incident Command Post | • Resource Location | • Structure Wrap | • Access or Improved Road | • SPI Gate | |

